

# **High-Precision Tuning Fork Electronic Balance**

# S J – E Series

# **Operation Manual**

# IMPORTANT

- To ensure safe and proper use of the balance, please read this manual carefully.
- After reading this manual, store it in a safe place near the balance, so you can review it as needed.

# SHINKO DENSHI CO., LTD.

# PREFACE

Thank you for purchasing an SJ Series electronic balance. This is a precision instrument equipped with exacting mechanisms in a compact body. The SJ series provides enhanced functions, including a counting mode for stock control of parts, a percentage mode for comparative measurements given in percentages, and a limit function for measuring constant quantities by consecutive weighings. Despite its many functions, the balance is easy to operate and features user-friendly keys. Furthermore, the large liquid-crystal display provides excellent visibility, and the instrument's high speed and stability–intrinsic to a tuning fork design–help boost operational efficiency.

Before using the balance, please check that the following items have been included in the package.

Should you find any missing parts, please contact your local dealer or our marketing division at once.

(1) Main unit of balance



(2) Measurement pan (one round or square pan)

Round pan




Square pan • SJ-1200E:170mm × 140mm • SJ-2200E ~ 12KE:180mm × 160mm

- (3) Pan base
   (one small for the round-pan balance; one large for the square-pan balance)
  - ound pan

for Round pan

for Square



• SJ-220E ~ 620E: 140mm





(5) Operation manual (one)

# CONTENTS

| 1. | Precautions on the Use2 |                                      |  |  |  |
|----|-------------------------|--------------------------------------|--|--|--|
| 2. | Name                    | es of Component Parts5               |  |  |  |
|    | 2.1                     | Main Unit5                           |  |  |  |
|    | 2.2                     | LCD Indicators and Operating Keys .6 |  |  |  |
| 3. | Basi                    | c Operations8                        |  |  |  |
|    | 3.1                     | Installation8                        |  |  |  |
|    | 3.2                     | Operation Check9                     |  |  |  |
|    | 3.3                     | Operation for Tare Subtraction10     |  |  |  |
| 4. | Func                    | tions12                              |  |  |  |
|    | 4.1                     | Setup and Checking of Functions12    |  |  |  |
|    | 4.2                     | Description of Functions13           |  |  |  |
|    | 4.3                     | Interface Section14                  |  |  |  |
| 5. | Swite                   | ching Functions for                  |  |  |  |
|    | U                       | nits of Measurement15                |  |  |  |
|    | 5.1                     | Switching Units of Measurement15     |  |  |  |

5.2 Setup of Units of Measurement ......15

| 6. | Cour  | ting Pieces   | 17 |
|----|-------|---|----|
|    | 6.1   | Sampling  | 17 |
|    | 6.2   | Increasing the Counting Accurac<br>(Memory Update Method) | •  |
| 7. | Meas  | suring Percentage   | 20 |
| 8. | Limit | Function  | 22 |
|    | 8.1   | Limit Function Setup                                      | 22 |
|    | 8.2   | Setup of Limit Values by Actual<br>Quantity Loads         | 24 |
|    | 8.3   | Setting up Limit Values by Inputt<br>Values               |    |
| 9. | Calib | rating the Balance  | 27 |
| 10 | . Tro | ubleshooting  | 29 |
| 11 | . Spe | cifications   | 30 |
|    | 11.1  | Basic Specifications                                      | 30 |
|    | 11.2  | 2 Common Specifications                                   | 30 |
|    | 11.3  | 3 Minimum Display by Unit of<br>Measurement               | 31 |
| 12 | . Con | version Table of Units                                    | 33 |

- This Section "Precautions Relating to Use" sets forth precautionary notes that the user should observe in order to prevent physical injury to the user and/or damage to property.
- The nature of problems that may result in the event of improper operation, and consequential effects on the quality and performance of the balance, are indicated under the two categories of "Caution" and "Recommended," and explained using symbols.



### RECOMMENDED

balance is used improperly. Be sure to observe these notes to ensure safe use of the balance as the improper use may cause serious results. This term indicates steps that the user should take to ensure the

This symbol indicates a risk of injury or property damage if the

This term indicates steps that the user should take to ensure the quality and reliability of the balance.

Meanings of Symbols Each symbol is accompanied by an instruction.



Indicates a "mandatory" action that should be executed without fail.





Symbol:

Indicates a "prohibited" action that must not be executed.



| Do Not<br>Disassemble             | <ul> <li>Do not disassemble or modify the unit.</li> <li>Could cause malfunction or heat generation</li> <li>Contact our Marketing Division or Technical<br/>Service Division.</li> </ul>                                 |
|-----------------------------------|---|
| Do Not<br>Deviate from<br>Ratings | <ul> <li>Only AC power (rated value) should be used.</li> <li>Only use the dedicated AC adapter.</li> <li>Use of other types of power or adapters may result in heat generation or malfunction of the balance.</li> </ul> |
| Do Not Move                       | <ul> <li>Do not move the balance when a sample is loaded.</li> <li>The loaded sample may fall off the measurement pan and cause an injury.</li> </ul>   |

| Do Not Use                      | Do not place the balance on an unstable base<br>or use the balance in a location where it may<br>be subjected to shock.  |
|---------------------------------|--|
| Do Not Drop                     | <ul> <li>Do not lay the AC adapter cable on the surface of the passage.</li> <li>Somebody may trip on the cable, causing the balance to fall off, thereby causing injury and/or damage to the balance.</li> </ul>                      |
| Do not Handle<br>with Wet Hands | <ul> <li>Do not touch the AC adapter or balance with wet hands.</li> <li>Danger of electric shock</li> </ul>   |
| Keep Dry                        | <ul> <li>Do not use the balance in a location were it may be subjected to excess moisture.</li> <li>Electric shock or short-circuiting could occur.</li> <li>The balance may be corroded, with resultant malfunction.</li> </ul>       |
| Do Not Leave<br>Afloat          | <ul> <li>Do not use the balance with its adjusters lifted.</li> <li>The balance will become unstable, preventing accurate measurement.</li> </ul>  |
| Avoid Dust                      | <ul> <li>Do not use the balance in a location where it may be subjected to excess dust.</li> <li>Risk of explosion or fire</li> <li>Short-circuit or lack of continuity may occur, leading to a malfunction of the balance.</li> </ul> |

RECOMMENDED






# Calibrate the balance after installation or relocation.

• Measurement values may contain errors, preventing accurate measurement from being conducted.

| Do Not Apply<br>Force |           | Avoid applying excess force or impact to the balance.   |
|-----------------------|-----------|---|
| Do Not Use            |           | <ul> <li>Do not use the balance in a location were it may be subjected to abrupt changes in ambient temperature or humidity.</li> <li>Accurate measurement may not be obtained.</li> <li>Optimum operations occur when ambient temperatures range from 5°C to 35°C, and less than 80% relative humidity.</li> </ul> |
| Do Not<br>Overload    | C C R D D | <ul> <li>Do not use the balance when [ - E ]<br/>(Overloaded) is displayed.</li> <li>Take down the loaded sample immediately to<br/>prevent breakage or malfunction.</li> </ul>   |
| Do Not Use            |           | <ul> <li>Do not use the balance in a location where it is subject to direct sunlight.</li> <li>The indications would be illegible.</li> <li>An internal temperature increase in the balance may lead to inaccurate measurement.</li> </ul>  |
| Unplug<br>Adapter     |           | <ul> <li>If the balance is to be unused for an extended period of time, unplug the adapter.</li> <li>This conserves power and prevents deterioration.</li> </ul>  |
| Do Not Use            |           | <ul> <li>Do not use volatile solvents for cleaning.</li> <li>The body may be distorted.</li> <li>To clean the unit of stains, use a piece of dry cloth or cloth soaked in a small quantity of neutral detergent.</li> </ul>   |
| Do Not Use            |           | <ul> <li>Do not use the balance in a location where it may be subject to air from an air-conditioning unit.</li> <li>Extreme changes in the ambient temperature may result in inaccurate measurements.</li> </ul>   |
| Do Not Use            |           | <ul> <li>Do not use the balance on a soft floor.</li> <li>When loaded with a sample, the balance may tip or move, preventing accurate measurements from being conducted.</li> </ul>   |
| Check Level           |           | <ul> <li>Do not use the balance when it is tilted.</li> <li>An inclined balance is likely to produce errors, preventing accurate measurements from being conducted. Place the balance on a level surface.</li> </ul>  |

#### 2.1 Main Unit

Round-pan types (SJ-220E ~ 620E) Square-pan types (SJ-1200E ~ 12KE)



## 2.2 LCD Indicators and Operating Keys

2.2.1 Symbols Displayed


#### 

| Display      | Description   |  |  |  |  |
|--------------|---|--|--|--|--|
| g            | Grams   |  |  |  |  |
| →0←          | Zero point  |  |  |  |  |
| NET          | Tare being subtracted   |  |  |  |  |
|              | Indication of stable balance (If the light is off, the balance is unstable.)    |  |  |  |  |
| *            | Balance powered up (Lights up when the power is turned off) or data transmitted |  |  |  |  |
| Pcs          | Counting mode   |  |  |  |  |
| %            | Percentage mode   |  |  |  |  |
| ▲            | Indication of judgement result (HI/OK/LO) when the limit function is active.    |  |  |  |  |
| mom          | Momme   |  |  |  |  |
| М            | Display of set values from memory (If a value is flashing, it is being saved.)  |  |  |  |  |
| CAL          | Stays on and flashes while span adjustment is in progress.                      |  |  |  |  |
| Omponyment E | Bar graph   |  |  |  |  |
|              | [ <b>c 七</b> ] (ct) carat   |  |  |  |  |
|              | [ OZ ] (oz) ounce   |  |  |  |  |
|              | [ ] (b) pound   |  |  |  |  |
| -dba-t       | [az t] (ozt) troy ounce   |  |  |  |  |
|              | [dvvt] ] (dwt) penny weight   |  |  |  |  |
|              | [▶(Upper right)] grain  |  |  |  |  |
|              | [+] (tl) tael (Hong Kong)   |  |  |  |  |
|              | [ + I ► Upper right ] (tl ► Upper right) tael (Singapore,Malaysia)              |  |  |  |  |
|              | [ ːːː ► Lower right ] (tl ► Lower right) tael (Taiwan)                          |  |  |  |  |
|              | [to] (to) tola  |  |  |  |  |


## 2.2.2 Names and Functions of Operating Keys

| Ор         | erating Key   |  | Function  |  |
|------------|---------------|--|---|--|
| On/off key |               | Key to turn on/off the unit power  |   |  |
| $\bigcirc$ | Memory key    | [Brief press]initiates print or output.[Brief press]saves the settings of the number of piece<br>percentages (%), or the limit value when<br>using the limit function. |   |  |
|            | Set key       | [Brief press]<br>[Continuous press]  | starts setting the number of pieces or<br>percentages (%).<br>starts setting the limit value when using the<br>limit function.  |  |
| Ø          | Function key  | [Brief press]<br>[Brief press]<br>[Brief press]<br>[Continuous press]<br>[Longer continuous press]   | toggle-switches the units to be displayed in<br>succession (g, Pcs, %, etc.).<br>moves the flashing digit in the setup of a limit<br>value when using the value input method.<br>selects an item when setting the function.<br>invokes various functions.<br>invokes span adjustment. |  |
| -0/T+-)    | Zero/Tare key | [Brief press]<br>[Brief press]<br>[Brief press]  | resets the indication to zero when using<br>zero-point setup or tare subtraction.<br>selects a value with the value input method<br>when using the limit function.<br>selects a function when operating the<br>balance in the function mode.  |  |

#### 3.1 Installation




## 3.2 Operation Check



## 3.3 Operation for Tare Subtraction

| 1 | Place the tare (container) on  | As you place the tare, the balance indicates its weight. |   |
|---|--------------------------------|--|---|
|   |                                | ••।।।⊧<br>2345g  |   |
| 2 | Reset read-out indication to z | ero.   | Press the Zero/Tare key.  |
|   |                                | 0 0.1.1   F NET<br>                                      | The tare is subtracted and the balance indicates zero.                                |
| 3 | Load the sample to be weight   | ed.<br>⁰⊡⊺FNET<br>5328g                                  | The balance will now indicate only<br>the weight of the sample loaded in<br>the tare. |

Weighing only the weight of an added sample



### Key Points of the Procedure


The following applies equally to all the measurement modes for weight measurement, counting, and percentages.

 After the balance is switched off, there is still enough current to display [\*]. This indicates that the AC adapter is connected to an electrical outlet, but that the balance is turned off. When the balance is switched on again, [\*] will disappear.

If the balance is running on batteries and the unit is switched off, the display does not display [\*].

 The bar graph shows the current load status with respect to the capacity of the balance. The nearer the [F] mark draws, the smaller the measurable weight becomes.

> Even when the display currently indicates zero with the tare subtracted, the weight corresponding to the subtracted tare is indicated on the bar.




3. When the balance remains stable, the stability indicator [ ] remains

on. If the balance becomes unstable, the stability indicator [ ] will disappear. When a displayed value flickers or the stability mark flashes on and off, it is likely that the balance is being affected by wind or other vibrations. Use the windshield or vibration dampers to protect against such adverse effects.



 When the read-out indicator is reset to zero or the tare is subtracted, the balance indicates zero this way: [→ 0 ←]. If the tare is subtracted, the indicator reads as follows: [NET].



- 5. When the tare is subtracted, the measurable range is reduced. Measurable Range = Capacity - Tare Weight
- 6. If  $[\Box \xi \tau]$  appears when a sample is loaded, the measurable range has been exceeded.
- 7. In counting mode or percentage mode, if no sample is stored in memory the indicator will not change, even when the measurement pan is pressed.
- 8. The measurement mode that is activated when the balance is switched on will be the one that was active when last switched off. For example, if the balance was switched off in counting mode, this counting mode will be reactivated the next time the balance is switched on.

# 4.1 Setup and Checking of Functions

| 1 | Invoking the function              | Press and hold down the<br>Function key until the indicator<br>changes to " $F \Box \Box \Box \Box$ ," then release<br>the key.<br>The function setup mode is activated,<br>and the first item,<br>[ $l = b. \Box$ , $l$ (Bar graph) 1] appears.<br>(See "4.2 Description of Functions"<br>on page 13.) |
|---|------------------------------------|---|
| 2 | Selecting the next item            | Press the Function key.<br>The indication changes to the next<br>item, [2:5 E L ] (Limit function)].  |
| 3 | Selecting an item                  | Pressing the Function key<br>advances the function items at the<br>rate of one item per press.  |
| 4 | Changing the content of an item    | Select the item to be changed with<br>the Function key.<br>Each press of the Zero/Tare key<br>changes the digit on the right end.<br>Select the desired one.  |
| 5 | Terminating the function selection | Press the Set key.<br>The balance terminates the function<br>setup and returns to measurement<br>mode.  |

# 4.2 Description of Functions

| Item   |                                      | Set Value      |                               | Description   |
|--|--------------------------------------|----------------|-------------------------------|---|
| Bar graph display  |                                      | ί Б.Б.         | <u></u> /                     | Disable<br>Enable   |
| Limit function   |                                      | 2.5 <i>E</i> L | <u></u> /                     | Disable<br>Enable   |
| n limit<br>ied   | Judgement condition                  | 2 (Co.         | ،<br>ح                        | Always judge (judges even when the balance is unstable)<br>Judge only when the balance is stable (does not judge<br>if the balance is unstable)   |
| Displayed only when limit<br>function is activated         | Judgement<br>range                   | 22.L i         | <i>D</i><br>/                 | Ranges beyond +5 graduation is judged (ranges +5<br>graduation or below, including negative ranges, are not<br>judged.)<br>The entire range is judged (the entire range, including<br>the negative, is judged). |
| Displa   | Number of<br>points for<br>judgement | 23.8 .         | ۱<br>ج                        | One-point setup (judges between OK and LO)<br>Upper-limit and lower-limit values are set up (judges<br>among HI, OK and LO).  |
|  | ito-zero<br>o-tracking)              | 3 R.O          | <u> </u>                      | DisableThis function automatically sets the zero pointEnableexactly to zero to prevent slight deviations.   |
| Auto   | power-off                            | 4 <i>RP</i> .  | <u></u> /                     | Not in function   |
| Response speed   |                                      | 5. r E.        | ם<br>ר<br>א<br>א<br>א<br>א    | Measurement by consecutive weighings.<br>Fast<br>↓<br>Slow  |
| Stability parameters                                       |                                      | 5. 5.d.        | ו<br>2<br>3<br>4              | Wide (mild)<br>↓<br>Narrow (strict)   |
| Interface  |                                      | 7. (F.         | 0<br> <br> <br>               | Disable input/output<br>Six-digit numeric format<br>Seven-digit numeric format  |
| Setup of units of<br>measurement to be<br>displayed        |                                      | 8 (5.u.<br>S   | 1 []  <br>2   4<br>  5<br>  5 | [g]<br>[ <b>cˈt</b> ] (ct)<br>[ <b>dz</b> ] (oz)<br>[ <b>1b</b> ] (lb)  |
| Register selected<br>measuring units with<br>Function key. |                                      | 85.5.0         | 10<br>17<br>18<br>19          | [ <b>□Z └</b> ] (ozt)<br>[ <b>□/ ヽ・亡</b> ] (dwt)<br>[ ► Lower right] (grain)  |

Items marked are the default factory settings.  $1 \sim 5$ : default settings  $[B \ (5 \ \mu)] \sim [B \ 5 \ 5 \ \mu]$ 

### 4.2 Description of Functions (cont.)

| Setup of                     | 1<br>8 (Su<br>855 | 18    | [ 🛃 ] (tl_Hong Kong)                       |
|------------------------------|-------------------|-------|--|
| measurement units            |                   | 15    | [ ᡶ ▶ Upper right] (tl_Singapore,Malaysia) |
| to be displayed <sup>1</sup> |                   | 1[    | [ ᡶ ▶ Lower right] (tl_Taiwan)             |
|                              |                   | 14    | [mom]                                      |
| Register                     |                   | 1E    | [ <b>七o</b> ](to)                          |
| measurement units            |                   | 3 2 🛛 | [ Pcs ]                                    |
| by selecting<br>Function key |                   | 4 1F  | [%]  |
|                              |                   | 5 🛛 🖓 | Unit not set                               |

1 ~ 5: default factory settings  $[B \ l \ 5 \ \mu] ~ [B \ 5 \ 5 \ \mu]$ 

1  $[\square \square]$  cannot be set at  $[\square \square]$ .

### 4.3 Interface Section

Displayed when [7, 1, F] is set to [1] or [2]

| Item           | Set Value            |          | Description   |                                       |  |  |  |   |  |
|----------------|----------------------|----------|---|---------------------------------------|--|--|--|---|--|
|                |                      | Π        | Stop output   |                                       |  |  |  |   |  |
|                |                      | 1        | Output continuous at all times  |                                       |  |  |  |   |  |
|                |                      | 2        | Output continuous if stable (stop output if unstable)   |                                       |  |  |  |   |  |
|                |                      | З        | Outputs once by pressing Memory key (irrespective of whether stable).   |                                       |  |  |  |   |  |
|                |                      | Ч        | Outputs once if stable. Outputs if the balance is stable<br>when a sample is loaded after the preceding sample has<br>been removed and the balance indicated zero, or less.                   |                                       |  |  |  |   |  |
| Output Control | η ίας.               | 5        | Outputs once if stable, and stops output when unstable.<br>Even if the sample is not replaced, the balance is output<br>once when it stabilizes next time (including the zero<br>indication). |                                       |  |  |  |   |  |
|                |                      |          |   |                                       |  |  |  | 5 | Outputs once if stable, and outputs continuously when<br>unstable. Even if the sample is not replaced, output of<br>the balance stops when it stabilizes after being output<br>once. |
|                |                      | 7        | Pressing <u>Memory</u> key causes the balance to output once when stable.   |                                       |  |  |  |   |  |
|                |                      | 1        | 1200 bps  |                                       |  |  |  |   |  |
| Baud Rate      | 72. Ь.L.<br>73. Р.R. | <u> </u> | 2400 bps  |                                       |  |  |  |   |  |
|                |                      | 3        | 4800 bps  |                                       |  |  |  |   |  |
|                |                      | 4        | 9600 bps  |                                       |  |  |  |   |  |
|                |                      |          | <u> </u>  | None Displayed only when [7, 1, 1, 2] |  |  |  |   |  |
| Parity         |                      |          | (7-digit numeric format)] is specified.   |                                       |  |  |  |   |  |
|                |                      | 2        | Even  |                                       |  |  |  |   |  |


denotes a factory-setting

The data interval in continuous output mode is 0.1 to 1 second. (The interval varies depending on weighting conditions and other factors.)

# 5. Switching Function for Units of Measurement

Pressing the Function key allows the user to switch the unit of measurement to [g], [ct], [%], and so on. During setup, a maximum of five different units can be registered for use in function setup mode.


### 5.1 Switching Units of Measurement




### 5.2 Setup of Units of Measurement

When values  $[B \ l \le \mu]$  to  $[B \ \le ...]$  are entered prior to use, the desired unit of measurement to be displayed can be chosen simply by pressing the Function key. For more information on the units of measurement that can be set here, please refer to "4.2 Description of Functions" on page 13.

# Example: To change the default factory settings to pound units, use [82.5...] in the factory settings.



# Example: To change the default factory settings to pound units use [ $B \supseteq S \sqcup$ ] in the factory settings. (cont.)




#### **Key Points of the Procedure**

- 1. When set values are entered in the function items [*B l* 5. *L*.] to [*B* 5. 5. *L*.] prior to use, the desired unit of measurement to be displayed can be selected simply pressing the Function key. For more information on the units of measurement that can be set, please refer to "4.2 Description of Functions," on page 13.
- 2. The units are displayed in the same sequence as the settings made from  $[B \ (5, \mu)]$  to  $[B \ 5, 5, \mu]$ .
- 3. If [[] []] is set, no unit of measurement will be displayed, even when units of measurement are set in subsequent items.
- 4.  $[\square \square]$  cannot be set in  $[\square \square \square \square]$ .
- 5. If the same unit of measurement is set multiple times, the second time (and all subsequent times) the unit(s) occurs, it will be ignored when the display switches.

To implement piece-counting, the specified samples are loaded on the balance, and their average unit weight (hereinafter, simply the "unit weight") is entered and saved. The procedure for saving unit weights is called sampling.

The counting procedure consists of loading articles that have already been sampled on to the balance. The number of pieces is then calculated by dividing the total weight of the loaded articles by the unit weight saved in memory. Piece counting cannot be implemented unless sampling has already taken place.



If samples to be counted deviate widely in weight, or a higher measure of accuracy is desired, it is recommended that users use the "Raising the Counting Accuracy" method. This procedure results in greater precision by increasing the number of samples used in the sampling operation.

### 6.1 Sampling

| 1 | Activating the counting mode     | Press the Function key to display [Pcs].  |
|---|----------------------------------|---|
|   | Pcs                              |   |
| 2 | Resetting the indication to zero | Place the tare and press the  |
|   |                                  | Zero/Tare key.<br>The tare is subtracted and the balance<br>now indicates zero.   |
| 3 | Starting the sampling            | Press the Set key.<br>The display flashes a number, such as $[\Box \cap I\Box]$ . This means that ten samples are to be loaded.<br>The sampling number that was used in the previous sampling will be displayed here. |

| 4 Changing the samplir  | ing number, if necessary.<br>How to change the value<br>100 $30100$ $3050$                         | If samples to be counted widely deviate<br>in weight, or a higher measure of<br>accuracy is desired, it is recommended<br>that users change the sampling number<br>to a larger value.<br>Press the Zero/Tare key.<br>Each press of the key changes the value on<br>the right end. Select the desired value.<br>If the sampling number need not be<br>changed, go on to the next step. |
|-------------------------|--|---|
| 5 Loading samples       |  | Load the number of samples displayed.   |
|                         | $ \begin{array}{c ccccccccccccccccccccccccccccccccccc$   | Count the samples precisely and load<br>them in the center of the measurement<br>pan.   |
| 6 Saving the unit weigh | t of samples   | Press the Memory key.   |
|                         | Pcs<br>B<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C<br>C | The balance saves the unit weight and reverts to measurement mode.  |

### Key Points of the Procedure

- 1. While the samples are being saved, the value indication disappears and only [M] flashes to indicate that memory saving is underway. If the balance is affected by wind or other vibrations during this process, the saving time may be prolonged.
- 2. If [L E r] appears, it indicates one of the following states:
  - The weight of one sample (measurable unit weight) is insufficient. For the range of unit weights that can be measured and saved, please refer to "11. Specifications," on page 30.
  - (2) In the sampling of Operation Step 3, press the Set key with the samples loaded on the balance.

```
If [\underline{l} - \underline{\beta} - \underline{r}] appears, the sampling is interrupted and the data in progress is not saved.
```


3. The operation for increasing counting accuracy is referred to as the Memory Update Method. This procedure updates the memory with a unit weight that represents a more precise average by gradually increasing the sampling number.

This operation improves counting accuracy and is recommended for the following cases;

- (1) When the samples to be counted deviate widely in weight or the number of samples displayed deviates.
- (2) When greater accuracy is desired.
- If [A ∠ ∠] appears in Memory Update Method, it indicates that a counting error is likely due to the small number of the samples loaded on the balance. [◄] will light up at the judgment indication "LO." As the memory update continues, counting accuracy improves and the above indication disappears.
- 5. If you change the sampling number, subsequent sampling will start from the new sampling number.

## 6.2 Increasing the Counting Accuracy (Memory Update Method)

This procedure is the same as the sampling procedure described on the previous page up, to the point at which the sampling number is changed.



The percentage measurement function operates by weighing an actual sample, selected as the reference, and saving its weight as the reference value and indexing it as 100%. When a measurement sample loaded on the balance is lighter or heavier than the reference, its weight is indicated as a percentage (%) value relative to the reference weight.

| 1 | Activating the percentage mode   | Press the Function key to disaplay [%].   |
|---|--|---|
|   |  |   |
| 2 | Setting the reference value  | Press the Set key.  |
|   | $\begin{array}{c} \begin{array}{c} & & \\ & \\ \end{array} \\ \hline \\ \\ \\ \end{array} \\ \hline \\ \\ \\ \\$ | The display begins flashing $[P, 5 E \ge ]$ . The balance is now ready for reference value setup.               |
| 3 | Loading the sample $\begin{array}{c} & & & \\ & & \\ \hline \\ & & \\ \hline \\ & & \\ \end{array}$  | Load the reference sample.  |
| 4 | Saving the reference value   | Press the Memory key.   |
|   |  | The balance indexes the weight value of<br>the reference sample as 100% and<br>returns you to measurement mode. |
| 5 | Loading a sample to be measured  | The balance now indicates the weight of the loaded sample as a percentage (%)                                   |
|   | 85.37 %  | value relative to the reference value.  |

### **Key Points of the Prcedure**

- 1. While samples are being saved, the value indication disappears temporarily, and only the [M] mark flashes. If the balance is affected by wind or other vibrations during this process, the saving time may be prolonged.
- 2. If [L E r] appears briefly, it indicates one of the following states:
  - The weight of the reference sample is insufficient. For the limit weight that can be saved (% limit weight), please refer to "11. Specifications," on page 30.
  - (2) While setting up the reference value in Step 2, the Set key has been pressed while the samples were loaded on the balance.

If [L - E - r] appears, sampling has been interrupted and the sample value being processed will not be saved.

3. The minimum intervals between percentages in the unit switch from 1%, to 0.1%, to 0.01%, depending on the reference weight from the sampling.

The limit function judges measurements according to a limit value saved in the balance.

The function shows the judgement result by displaying the [◀] mark as either HI (excessive), OK (appropriate), or LO (insufficient). This function is very useful when discriminating between conforming and nonconforming articles. It is also useful when measuring a given constant quantity consecutively, in conjunction with a range of reference weights defined by upper- and lower-limit values.

This function can be used in weight mode, counting mode, or percentage mode.

#### Limit value input methods

Either of the following two methods can be used in the different modes:

- (1) Actual quantity setup method ...... An actual sample is loaded on the balance and its weight saved as the limit value.
- (2) Numeric value setup method ....... The limit value is entered with a key stroke.

The limit values entered are held in memory, even when the balance is powered down.


The respective limit values for weight mode, counting mode, and percentage mode are set up independently.

#### Indication of judgement result


The [**4**] mark lights up as either HI, OK, or LO on the left side of the display, indicating the result of judgement.

| Judgement Results | Upper/lower-limit setting                                    | One-point setting               |
|-------------------|--|---------------------------------|
| HI (excessive)    | Upper-limit value < measurement<br>value                     | No indication                   |
| OK (appropriate)  | Upper-limit value ≥ measurement<br>value ≥ lower-limit value | Limit value ≤ measurement value |
| LO (insufficient) | Lower-limit value > Measurement value                        | Limit value > Measurement value |

### 8.1 Limit Function Setup



## 8.1 Limit Function Setup (cont.)



# 8.2 Setup of Limit Values by Actual Quantity Loads

| 1 Starting the limit function   | Press and hold down the Set key.   |
|---|--|
| Continuous pressing Key released  | Release the key when $[\_ 5 \_ 2 \_]$ is displayed.<br>The currently set lower-limit value flashes.  |
| 2 Loading the sample for the lower-limit value                              | Load the sample of the lower-limit value<br>on the measurement pan.  |
| 3 Saving the lower-limit value  | Press the <u>Memory</u> key.<br>After the lower-limit value has been<br>saved, the balance displays it briefly and<br>proceeds to the following setup.<br>If One-point setup was chosen, the<br>setup is complete. |
| 4 The upper-limit<br>value setup<br><i>H</i> 5 <i>E L L L L L L L L L L</i> | The display now changes to $[H, 5E_{L}]$ , indicating that the upper-limit value can be set.<br>The currently set upper-limit value flashes.   |
| 5 Loading the sample of the upper-limit value                               | Load the sample of the upper-limit value<br>on the measurement pan.  |
| 6 Saving the upper-limit value  | Press the Memory key.<br>After saving the upper-limit value, the<br>balance displays it briefly and terminates<br>the setup.   |

# 8.3 Setting up Limit Values by Inputting Values


| 1 Starting the limit function   | Press and hold down the Set key.   |
|---|--|
|   | Release the key when $[\underline{L}, \underline{SEE}]$ is displayed.<br>The currently set lower-limit value   |
| Continuous pressing Key released  | flashes.   |
| 2 Opening the value input screen  | Press the Zero/Tare key.   |
|   | All the digits are displayed, with the one<br>on the right end flashing. This flashing<br>digit is the one that can be changed.  |
| 3 Entering a value  | Press the Zero/Tare key again.<br>Pressing the key repeatedly changes the<br>flashing value until the desired number is<br>entered.  |
| 4 Selecting a digit   | Press the Function key.<br>The flashing moves to the digit on the<br>immediate left. Each time the key is<br>pressed, the flashing digit moves one<br>position left. When the leftmost digit is<br>selected, the flashing advances to the<br>rightmost digit position. |
| 5 Repeat Steps 3 and 4  | Enter the lower-limit value by selecting a value with the Zero/Tare key and moving the digits with the Function key, as needed.  |
| 6 Saving the lower-limit value  | Press the Memory key.<br>After saving the lower-limit value, the<br>balance displays it briefly and proceeds<br>to the next setup.<br>If one-point setup was chosen, the<br>setup is complete.   |
| 7 Setting up the upper-limit value $H  SEE \qquad \qquad$ | The display changes to $[H, 5 E E]$ ,<br>indicating that the upper-limit value can<br>be set.<br>If there is an upper-limit value already<br>set, that value will flash.   |

### 8.3 Setting up Limit Values by Inputting Values (cont.)

| 8  | Opening the value input screen  | Press the Zero/Tare key.<br>Follow the same procedure as in "Step<br>2."   |
|----|---|--|
| 9  | Setting the upper-limit value $ \begin{bmatrix}                                   $ | Follow the same procedure as described<br>for the lower-limit value and enter the<br>upper-limit value.                  |
| 10 | Saving the upper-limit value  | Press the Memory key.<br>After saving the upper-limit value, the<br>balance displays it briefly and terminates<br>setup. |

### **Key Points of the Procedure**

1. The limit values you have set can be checked each time you press the <u>Set</u> key. The balance displays the lower-limit value after showing [L. 5EE], and the upper-limit value after showing [H 5EE].




- 2. If you make a mistake, press the Function key during the setup of actual quantities or the Set key during the setup of values.
- 3. If you press the Memory key while a value is flashing, an actual quantity will be set based on the weight currently loaded on the balance. Pressing the Zero/Tare key at this time displays the value input screen.
- 4. If the [◀] mark lights up for all three judgement indicators, HI, OK, and LO, the lower-limit value set exceeds the upper-limit value. Check the values, since mistakes can occur with entries, as in cases when the upper-limit value is specified with a negative sign.
- 5. When the [M] mark is flashing on the value input screen, the sign on the left end can be changed. Press the Zero/Tare key to switch between the positive and negative signs.

Since electronic balances are affected by gravity gravitational acceleration, they produce different values in various locations. Therefore, before use, balances must be calibrated at the location where they are installed. Calibration is also required after long periods without use, or if a balance begins to produce inaccurate values.

Calibration of a balance, or "span adjustment," is required to produce accurate measurements.

Span adjustment should be performed with the balance installed perfectly level and without any load on the measurement pan.



#### Calibrating the Balance (cont.)

| 4 | Calibrating the capacity po | bint<br>$\downarrow \downarrow \downarrow \downarrow \bigcirc CAL$<br>$\square n F.5$<br>$\downarrow \downarrow \downarrow \downarrow$ | Load the calibration weight in the center<br>of the balance.<br>The display flashes, indicating that<br>capacity point calibration is in progress. |
|---|-----------------------------|--|--|
| 5 | Terminating the span adjust | stment   | When the calibration of the capacity<br>point is finished, the original<br>measurement mode is restored.   |

### Key Points of the Procedure

- 1. Pressing the Function key in Step 2 interrupts the span adjustment and returns you to the original measurement mode.
- 2. The calibration weight used for span adjustment should be heavier than half the capacity of the balance.

To implement a calibration as precisely as possible, use a weight close to the capacity of the balance.

Calibration weights can be ordered from Shinko. For ordering information, please contact Shinko.

- 3. If problems arise during span adjustments, one or more of the following error messages will appear:
  - (1)  $[\Box E r]$ : The calibration weight exceeds the capacity of the balance.
  - (2) [l E r]: The calibration weight is less than half the capacity of the balance.
  - (3)  $[\vec{r} \vec{E} \vec{r}]$ : The difference between before and after calibration values is too large (1.0% or more).

If error messages are displayed, calibration cannot take place.

Check the weight and re-calibrate. If the same error continues after repeated calibrations using the correct weight, please contact our Marketing Division or Technical Service Division.

| Symptom  | Cause   | Possible remediation   |
|--|---|--|
| There is no indication on the display.   | The AC adapter is not connected.  | $\rightarrow$ Check that the AC adapter is connected (8).  |
| The display is unstable.<br>[M] remains flashing<br>without changing.  | <ul> <li>The balance is subject to air currents or vibration.</li> <li>The balance is situated on an unstable surface.</li> <li>An object is contacting the sample being measured, the measuring pan, or the tare.</li> </ul>   | → Check Precautions on<br>Use (2–4).   |
| Weight indication contains an error.   | <ul> <li>An error was made in the tare subtraction procedure.</li> <li>The adjusters remain lifted, resulting in an incorrect level.</li> <li>The indication values are inconsistent after long hours of use, or because the balance has been moved to a new location.</li> </ul> | <ul> <li>→ Review the tare<br/>subtraction (10).</li> <li>→ Check the level (8).</li> <li>→ Execute span adjustment<br/>on the balance (27).</li> </ul>          |
| The limit function does not work.  | <ul> <li>The limit function is not selected.</li> <li>The limit value has been erroneously entered.</li> </ul>  | → Check the operation of the limit function (22 on).   |
| [ <i>R 占 占</i> ] appears ([◀]<br>and a value flash at<br>[LO].)  | <ul> <li>Likely to produce errors in the counting<br/>mode because the sample weight is<br/>insufficient.</li> </ul>  | → Execute the Memory<br>Update Method (19).  |
| $[ \ E ]$ appears<br>before the capacity is<br>reached.  | <ul> <li>Gross weight exceeded the capacity of the balance (weight range = container + weight of sample).</li> <li>A section of the mechanism is damaged.</li> </ul>  | <ul> <li>→ Check the total weight.</li> <li>→ Execute tare subtraction again.</li> <li>→ Contact our Technical Service Division or your local dealer.</li> </ul> |
| [ <i>山 - 左 - r</i> -] is<br>displayed.   | <ul> <li>A foreign object is caught between the measuring pan (pan base) and the balance.</li> <li>A section of the mechanism is damaged.</li> </ul>  | → Remove the measurement<br>pan and examine the<br>surface beneath it.   |
| [ <i>占 - E -                                </i>   | <ul> <li>The balance is exposed to static electricity<br/>or noise.</li> <li>The electrical system of the balance is<br/>malfunctioning.</li> </ul>   | → Contact our Technical<br>Service Division or your<br>local dealer.   |
| During span adjustment<br>$[\Box - E - r]$ is<br>displayed.<br>[I - E - r] is<br>displayed.<br>$[\overline{L} - E - r]$ is<br>displayed. | <ul> <li>A weight heavier than the capacity was used.</li> <li>The reference weight is less than 50% of the capacity.</li> <li>Calibration produced an error of 1.0% or more.</li> </ul>  | → Check that the span<br>adjustment procedure<br>was performed correctly<br>(27).  |

The numbers in ( ) indicate reference pages

# 11.1 Basic Specifications

| Model  | SJ-220E                          | SJ-420E | SJ-620E | SJ-1200E |
|--|----------------------------------|---------|---------|----------|
| Capacity [g]                                   | 220                              | 420     | 620     | 1200     |
| Readability [g]                                | 0.01                             | 0.01    | 0.01    | 0.1      |
| Measurable unit weight in<br>counting mode [g] | 0.01                             | 0.01    | 0.01    | 0.1      |
| Minimum weight in percentage<br>mode [g]       | 1                                | 1       | 1       | 10       |
| Weight measuring method                        | Tuning fork vibration method     |         |         |          |
| Calibration method                             | With external calibration weight |         |         |          |
| Pan Size [mm]                                  | φ140 170x140                     |         | 170x140 |          |
| Output   | Option(RS232C)                   |         |         |          |
| Windshield                                     | Not provided                     |         |         |          |

| Model  | SJ-2200E                         | SJ-4200E | SJ-6200E | SJ-12KE |
|--|----------------------------------|----------|----------|---------|
| Capacity [g]                                   | 2200                             | 4200     | 6200     | 12000   |
| Readability [g]                                | 0.1                              | 0.1      | 0.1      | 1       |
| Measurable unit weight in<br>counting mode [g] | 0.1                              | 0.1      | 0.1      | 1       |
| Minimum weight in percentage<br>mode [g]       | 10                               | 10       | 10       | 100     |
| Weight measuring method                        | Tuning fork vibration method     |          |          |         |
| Calibration method                             | With external calibration weight |          |          |         |
| Pan Size [mm]                                  | 180x160                          |          |          |         |
| Output   | Option(RS232C)                   |          |          |         |
| Windshield                                     | Not provided                     |          |          |         |

# **11.2 Common Specifications**

|     | -  |  |
|-----|--|--|
| (1) | Weight measuring method                    | Tuning fork vibration method   |
| (2) | Tare subtraction range                     | Total capacity   |
| (3) | Liquid-crystal display (LCD)               | Seven segments (two segments in leading part) ,<br>Maximum digits indication: seven digits,<br>Segment height: 16.5 mm, with back light. |
| (4) | Measuring function                         | Weight mode, counting mode, and percentage mode  |
| (5) | Overload indication                        | $[\Box - E - \tau]$ is displayed if weight capacity + 9 intervals are exceeded.  |
| (6) | Compatible printer                         | CSP-160  |
| (7) | Operating temperature and humidity ranges. | 5°C to 35°C, 80%RH or less   |
| (8) | AC adapter                                 | Dedicated AC adapter:100V - 230V AC / 9V-12V DC  |
|     |  |  |

# 11.3 Minimum Display by Unit of Measurement

| Model                    |         |         |         |          |
|--------------------------|---------|---------|---------|----------|
| Unit_of                  | SJ-220E | SJ-420E | SJ-620E | SJ-1200E |
| measurement              |         |         |         |          |
| a                        | 220     | 420     | 620     | 1200     |
| g                        | 0.01    | 0.01    | 0.01    | 0.1      |
| ርቲ (ct)                  | 1100    | 2100    | 3100    | 6000     |
|                          | 0.05    | 0.05    | 0.05    | 0.5      |
| <b>07</b> (oz)           | 7.7     | 14      | 21      | 42       |
|                          | 0.0005  | 0.0005  | 0.0005  | 0.005    |
| <b>//</b> (Ib)           | 0.48    | 0.92    | 1.3     | 2.6      |
| <b>ib</b> (lb)           | 0.00005 | 0.00005 | 0.00005 | 0.0005   |
| ወ፤ ቲ (ozt)               | 7       | 13      | 19      | 38       |
|                          | 0.0005  | 0.0005  | 0.0005  | 0.005    |
| dייל (dwt)               | 140     | 270     | 390     | 770      |
|                          | 0.01    | 0.01    | 0.01    | 0.1      |
| ► (grain)                | 3300    | 6400    | 9500    | 18000    |
| (grain)                  | 0.2     | 0.2     | 0.2     | 2        |
| 七/                       | 5.8     | 11      | 16      | 32       |
| (Hong Kong)              | 0.0005  | 0.0005  | 0.0005  | 0.005    |
| 七/                       | 5.8     | 11      | 16      | 31       |
| (Singapore,<br>Malaysia) | 0.0005  | 0.0005  | 0.0005  | 0.005    |
| <b>ti</b> (Taiwan)       | 5.8     | 11      | 16      | 32       |
|                          | 0.0005  | 0.0005  | 0.0005  | 0.005    |
| mom                      | 58      | 110     | 160     | 320      |
| (momme)                  | 0.005   | 0.005   | 0.005   | 0.05     |
| <b>±o</b> (to)           | 18      | 36      | 53      | 100      |
|                          | 0.001   | 0.001   | 0.001   | 0.01     |

The view of the table

Upper cell : Capacity Lower cell : Readability

| Model<br>Unit_of<br>measuremant | SJ-2200E | SJ-4200E | SJ-6200E | SJ-12KE |
|---------------------------------|----------|----------|----------|---------|
| a                               | 2200     | 4200     | 6200     | 12000   |
| g                               | 0.1      | 0.1      | 0.1      | 1       |
| <b>ርቲ</b> (ct)                  | 11000    | 21000    | 31000    | 60000   |
|                                 | 0.5      | 0.5      | 0.5      | 5       |
| <b>07</b> (oz)                  | 77       | 140      | 210      | 420     |
|                                 | 0.005    | 0.005    | 0.005    | 0.05    |
| <b>Њ</b> (Ib)                   | 4.8      | 9.2      | 13       | 26      |
| <b>ib</b> (lb)                  | 0.0005   | 0.0005   | 0.0005   | 0.005   |
| वर द (ozt)                      | 70       | 130      | 190      | 380     |
|                                 | 0.005    | 0.005    | 0.005    | 0.05    |
| dייל (dwt)                      | 1400     | 2700     | 3900     | 7700    |
|                                 | 0.1      | 0.1      | 0.1      | 1       |
| ► (grain)                       | 33000    | 64000    | 95000    |         |
|                                 | 2        | 2        | 2        |         |
| 七!                              | 58       | 110      | 160      | 320     |
| (Hong Kong)                     | 0.005    | 0.005    | 0.005    | 0.05    |
| ti                              | 58       | 110      | 160      | 310     |
| (Singapore,<br>Malaysia)        | 0.005    | 0.005    | 0.005    | 0.05    |
| t (Taiwan)                      | 58       | 110      | 160      | 320     |
| τί (Taiwan)                     | 0.005    | 0.005    | 0.005    | 0.05    |
| mom                             | 580      | 1100     | 1600     | 3200    |
| (momme)                         | 0.05     | 0.05     | 0.05     | 0.5     |
| <b>to</b> (to)                  | 180      | 360      | 530      | 1000    |
|                                 | 0.01     | 0.01     | 0.01     | 0.1     |

The view of the table

Upper cell : Capacity Lower cell : Readability

# 12. Conversion Table of Units

| Unit          | Gram      | carat      | Ounce   | Pound   | troy ounce | Penny<br>Weight |
|---------------|-----------|------------|---------|---------|------------|-----------------|
| 1g            | 1         | 5          | 0.03527 | 0.00220 | 0.03215    | 0.64301         |
| 1ct           | 0.2       | 1          | 0.00705 | 0.00044 | 0.00643    | 0.12860         |
| 1oz           | 28.34952  | 141.74762  | 1       | 0.06250 | 0.91146    | 18.22917        |
| 1lb           | 453.59237 | 2267.96185 | 16      | 1       | 14.58333   | 291.66667       |
| 1ozt          | 31.10348  | 155.51738  | 1.09714 | 0.06857 | 1          | 20              |
| 1dwt          | 1.55517   | 7.77587    | 0.05486 | 0.00343 | 0.05       | 1               |
| 1GN           | 0.06480   | 0.32399    | 0.00229 | 0.00014 | 0.00208    | 0.04167         |
| 1tl (HK)      | 37.429    | 187.145    | 1.32027 | 0.08252 | 1.20337    | 24.06741        |
| 1tl (SGP,Mal) | 37.79936  | 188.99682  | 1.33333 | 0.08333 | 1.21528    | 24.30556        |
| 1tl (Taiwan)  | 37.5      | 187.5      | 1.32277 | 0.08267 | 1.20565    | 24.11306        |
| 1mom          | 3.75      | 18.75      | 0.13228 | 0.00827 | 0.12057    | 2.41131         |
| 1to           | 11.66380  | 58.31902   | 0.41143 | 0.02571 | 0.37500    | 7.5             |

| unit          | Grain     | tael<br>(Hong Kong) | tael<br>(Singapore,<br>Malaysia) | tael<br>(Taiwan) | momme     | Tola     |
|---------------|-----------|---------------------|----------------------------------|------------------|-----------|----------|
| 1g            | 15.43236  | 0.02672             | 0.02646                          | 0.02667          | 0.26667   | 0.08574  |
| 1ct           | 3.08647   | 0.00534             | 0.00529                          | 0.00533          | 0.05333   | 0.01715  |
| 1oz           | 437.5     | 0.75742             | 0.75                             | 0.75599          | 7.55987   | 2.43056  |
| 1lb           | 7000      | 12.11874            | 12                               | 12.09580         | 120.95797 | 38.88889 |
| 1ozt          | 480       | 0.83100             | 0.82286                          | 0.82943          | 8.29426   | 2.66667  |
| 1dwt          | 24        | 0.04155             | 0.04114                          | 0.04147          | 0.41471   | 0.13333  |
| 1GN           | 1         | 0.00173             | 0.00171                          | 0.00173          | 0.01728   | 0.00556  |
| 1tl (HK)      | 577.61774 | 1                   | 0.99020                          | 0.99811          | 9.98107   | 3.20899  |
| 1tl (SGP,Mal) | 583.33333 | 1.00990             | 1                                | 1.00798          | 10.07983  | 3.24074  |
| 1tl (Taiwan)  | 578.71344 | 1.00190             | 0.99208                          | 1                | 10        | 3.21507  |
| 1mom          | 57.87134  | 0.10019             | 0.09921                          | 0.1              | 1         | 0.32151  |
| 1to           | 180       | 0.31162             | 0.30857                          | 0.31103          | 3.11035   | 1        |